A Cicada Studio *Tutorial:* How To Make Threaded Fabric Bunting



What you’ll need:

fabrics • scissors • pins • sewing machine/thread • boning tool (or similar)
iron • cording or ribbon, etc. • pencil or threading rod • tape

- Start by folding fabric, right sides together, so that you can align top of template with folded edge.
- Cut as many pennant pieces as you desire. Pin to keep from slipping. Mark the dots with pins or light pencil.
- Stitch 1/4” from edge between the two dots. Back tack at each dot but *don’t go beyond that point*!
- Trim tip of triangle and turn inside out through the one of the openings at top. Using boning tool helpful.
- Use boning tool to create neat tip
- As you smooth out with your fingers to reshape the triangle and smooth seams, tuck in unsewn edges at the hole openings as indicated by red lines
- Press
- Topstitch 1/4” from top edge
- Thread cording through holes and make a loop at each end to hang.

Typical fat quarter is 18” high/9” when folded..
This pattern will fit, only the tip may get cut off.
No biggie, since you’ll snip it after sewing anyway.

You can always reduce the size of this template a little bit, too, but make sure you leave an inch wide opening at the top!

1.21.10